

Portion 56 of  
Farm Chelsea No. 23





Environmental  
Sensitivity

Legend





Structures

-  Existing Structure
-  Proposed Development Footprint
-  Existing Pool
-  Fence Line
-  Telephone Line




Water Infrastructure


-  Existing Underground Water Tank
-  Existing Borehole
-  Proposed Borehole
-  Proposed Water Pipeline

Sewerage Infrastructure

-  Proposed Sewer Pipeline
-  Proposed Septic Tank
-  Existing Sewer Pipeline
-  Existing Septic Tank

Eco Sens

-  Low Ecological Sensitivity
-  Moderate Ecological Sensitivity
-  Not Ecologically Sensitive








Christelle du Plessis (Pr. Sci. Nat.)  
Environmental Consultant  
christelle@habitatlink.co.za  
074 148 5583  
www.habitatlink.co.za

Portion 56 of  
Farm Chelsea No. 23





Environmental  
Sensitivity

Legend





Structures

-  Existing Structure
-  Proposed Development Footprint
-  Existing Pool
-  Fence Line
-  Telephone Line




Water Infrastructure

-  Existing Underground Water Tank
-  Existing Borehole
-  Proposed Borehole
-  Proposed Water Pipeline

Sewerage Infrastructure

-  Proposed Sewer Pipeline
-  Proposed Septic Tank
-  Existing Sewer Pipeline
-  Existing Septic Tank

Eco Sens

-  Low Ecological Sensitivity
-  Moderate Ecological Sensitivity
-  Not Ecologically Sensitive

